


Product Update Notice

RCS Sure Actuators

Sure Power 115V Power On Brake – Part#71-24

September 23, 2019

Product Update Notices provide information about updates, enhancements, improvements, certifications and other changes to new and current Dresser Industrial Products Group. The information in these notices is intended to help you take advantage of the continuous improvements to Dresser Industrial



Products Group and services.

Product Update Overview

No changes in brake adjustment for Sure power actuator line with all approved brakes – **Part# 71-24**.

Brake set gap assembly continues to be between 0.011" & 0.013". It is highly recommended to use a gage during installation to obtain an accurate gap during brake adjustment. A 0.012" gage is highly recommended.

User Benefits

It is highly recommended to use a gage during installation to obtain an accurate gap during brake adjustment. **A 0.012” gage is highly recommended.**

Support Contacts

For further information, you may contact:

- Your Dresser NGS Sales Manager
- Call us at Phone 832-590-2306, or toll-free number 1-800-945-9898
- Via email at rcs.info@dresserngs.com / andco.info@dresserngs.com / txt.info@dresserngs.com

You may also visit us dresserngs.com/ .

Life Cycle Program Overview

- Due to dual sourcing needs, ECN(Engineering Change Notice)#66095 approved Thomson Deltran brake (Vendor Part#BF-15J) to be used on our RCS Product line. This brake is interchangeable with our existent brake. Part#71-24 changed revision to D.
- Alternate brake from Thompson Deltran meets the all engineering specifications for our product. Brakes are 1 to 1 replacement. No form fit and function has been violated.
- Alternate brake from Thompson Deltran was tested and evaluated for our actuators.
- Brake was properly tested and added in all required certificate of conformance.

Affected Parts List

All RCS Sure product line used brake part#71-24: Sure 24/25/65/100 & 150